

Fire Alarm and Life Safety System Inspection Certificate

For

Kerry's Place

Building Number: 1543572

Tested to CAN/ULC S536-04 Standard
Smoke alarms are inspected to CAN ULC S553-02

This report should be accompanied by the BRForm containing the contents of CAN/ULC S536-04 Appendix E

This Inspection was performed in accordance with applicable ULC Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.


The devices in this report are 100% tested and 100% passed

Annual Inspection


Start Date: Oct 21, 2025

End Date: Oct 21, 2025

Service - Tested



Building: Kerry's Place
Contact: MAIN .



Company: Georgian Bay Fire & Safety - Peterborough
Contact: Derek Rennie

To obtain further details about this inspection please utilize your login and password to view online.
This FireScan report should be accompanied with the associated BRForm.

Fire Alarm Testing Report

Executive Summary

Generated by: BuildingReports.ca

Building Information

Building: Kerry's Place

Contact: MAIN .

Address:

Phone: .

Address:

City/Province/Postal Code:

Email: accountspayable@kerrysplace.org

Inspection Performed By

Company: Georgian Bay Fire & Safety - Peterborough

Inspector: Derek Rennie

Address: 347 Pido Road

Phone: 1-800-265-3197

Address: Unit 19

City/Province/Postal Code: Peterborough, Ontario K9J 6X7

Email: derek.rennie@fire-sp.com

Certification

Company: Georgian Bay Fire & Safety - Peterborough


Building: Kerry's Place

Inspector: Derek Rennie

Contact: MAIN .



Signed: Oct 20, 2025



Signed: Oct 20, 2025

Individual Device Record

Generated by: BuildingReports.ca

Type of Inspection: Fire Alarm System Annual Inspection and Test (ULC S536-04)

Building Name: Kerry's Place

Inspection Date and Time: 10/21/25 10:56:41 AM

Inspector: Derek Rennie

Note: The Location Column includes the location, time and date of the inspection and barcode number.

Remarks Column: Detector sensitivity in percentage and Waterflow Switch time delay in seconds.

For specific output circuit operation confirmation see associated BRForm section - "Ancillary Function Testing"

Location	Device Type	Correctly Installed	Requires Service, Repairs, Cleaning or Missing	Alarm Operation Confirmed	Annunciation Indication Confirmed	Zone Circuit Number or Address	Supervision of Wiring Device Confirmed	Ground Circuit Confirmed	Remarks/ Readings
<i>Tested</i>									
Basement North, 10:56:41AM 10/21/2025 (A0248221)	Smoke Alarm	☒	☐	☐	☐	1- Interconnected	☐	☐	LTD 10/21 /2025
1st At Bedrooms, 10:36:52AM 10/21/2025 (A0248218)	Smoke Alarm	☒	☐	☐	☐	1- Interconnected	☐	☐	LTD 10/21 /2025
1st North/East Bedroom#1, 10:37:42AM 10/21/2025 (A0248211)	Smoke Alarm	☒	☐	☐	☐	1	☐	☐	LTD 10/21 /2025
1st Rear Storage, 10:52:11AM 10/21/2025 (A0248220)	Smoke Alarm	☒	☐	☐	☐	1- Interconnected	☐	☐	LTD 10/21 /2025
1st South/East Bedroom#2, 10:39:12AM 10/21/2025 (A0248212)	Smoke Alarm	☒	☐	☐	☐	1	☐	☐	LTD 10/21 /2025
1st Kitchen (Barcode on Doorframe), 10:53:55AM 10/21/2025 (A0248210)	Smoke Alarm	☒	☐	☐	☐	1- Interconnected	☐	☐	LTD 10/21 /2025
2nd Top of Stair, 10:47:18AM 10/21/2025 (A0248219)	Smoke Alarm	☒	☐	☐	☐	1	☐	☐	LTD 10/21 /2025

Inspection & Testing

Generated by: BuildingReports.ca

Building: Kerry's Place			Control Panel: 1	
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
<i>Passed</i>				
Initiating				
Smoke Alarm	Basement North	Tested	10:56:41 AM	10/21/2025
Smoke Alarm	1st At Bedrooms	Tested	10:36:52 AM	10/21/2025
Smoke Alarm	1st Kitchen (Barcode on Doorframe)	Tested	10:53:55 AM	10/21/2025
Smoke Alarm	1st North/East Bedroom#1	Tested	10:37:42 AM	10/21/2025
Smoke Alarm	1st Rear Storage	Tested	10:52:11 AM	10/21/2025
Smoke Alarm	1st South/East Bedroom#2	Tested	10:39:12 AM	10/21/2025
Smoke Alarm	2nd Top of Stair	Tested	10:47:18 AM	10/21/2025

Smoke Alarms

Generated by: BuildingReports.ca

Building: Kerry's Place				
The smoke alarm report details the inspection of smoke alarms.				
Scan ID	Location	Type	Voltage	Mfr. Date
Passed				
A0248221	Basement North	Combo SA/CO	110V/Bat	11/29/2018
A0248218	1st At Bedrooms	Combo SA/CO	110V/Bat	11/29/2017
A0248210	1st Kitchen (Barcode on Doorframe)	Ionization	110V/Bat	10/21/2023
A0248211	1st North/East Bedroom#1	Ionization	9V	11/29/2023
A0248220	1st Rear Storage	Combo SA/CO	110V/Bat	11/29/2018
A0248212	1st South/East Bedroom#2	Ionization & Photoelectric	9V	11/29/2023
A0248219	2nd Top of Stair	Ionization	9V	11/29/2024

Inventory & Warranty Report

Generated by: BuildingReports.ca

Building: Kerry's Place				Control Panel: 1
<i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i>				
Device or Type		Category	% of Inventory	Quantity
Smoke Alarm		Initiating	100.00%	7
Type	Qty	Model #	Description	Install Date
<i>New (under 90 days)</i>				
Kidde				
Smoke Alarm	1	i12040ACA	Ionization	10/21/2025
<i>In Service - 90 Days - 1 Year</i>				
Kidde				
Smoke Alarm	1	i9010CA	Ionization	11/29/2024
<i>In Service - 1 Year to 2 Years</i>				
Kidde				
Smoke Alarm	1	PI9010CA	Ionization & Photoelectric	11/29/2023
Smoke Alarm	1	i9010CA	Ionization	11/29/2023
<i>In Service - 5 Years to 10 Years</i>				
Kidde				
Smoke Alarm	1	KN-COPE-ICCA	Combo SA/CO	11/29/2018
Smoke Alarm	1	KN-COPE-ICCA (900-0	Combo SA/CO	11/29/2018
Smoke Alarm	1	KN-COPE-ICCA	Combo SA/CO	11/29/2017

Safety Equipment Inspection Report

For

Kerry's Place

Building Number: 1543572

This Inspection was performed in accordance with applicable standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

The devices in this report are 100% tested and 75% passed

*Annual Inspection
Inspection Date
Oct 21, 2025*



Building: Kerry's Place
Contact: MAIN .



Company: Georgian Bay Fire & Safety - Peterborough
Contact: Derek Rennie
Safety Equipment Report

Executive Summary

Generated by: BuildingReports.ca

Building Information

Building: Kerry's Place

Contact: MAIN .

Address:

Phone: .

Address:

City/Province/Postal Code:

Email: accountspayable@kerrysplace.org

Inspection Performed By

Company: Georgian Bay Fire & Safety - Peterborough

Inspector: Derek Rennie

Address: 347 Pido Road

Phone: 1-800-265-3197

Address: Unit 19

City/Province/Postal Code: Peterborough, Ontario K9J 6X7

Email: derek.rennie@fire-sp.com

Inspection Summary

Category:	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Fire	5	62.50%	5	100.00%	4	80.00%	1	20.00%
Lighting	3	37.50%	3	100.00%	2	66.67%	1	33.33%
Totals	8	100%	8	100.00%	6	75.00%	2	25.00%

Certification

Company: Georgian Bay Fire & Safety - Peterborough


Building: Kerry's Place

Inspector: Derek Rennie

Contact: MAIN .



Signed: Oct 20, 2025



Signed: Oct 20, 2025

Discrepancy Report with Proposed Solutions

Generated by: BuildingReports.ca

Building: Kerry's Place								
<i>This report consolidates all discrepancies and provides proposed solutions to these issues. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any devices that have been corrected and passed the retest are checkmarked under the Fixed column and details regarding the individual who completed the fix are noted in the last column. Any item that was inspected that is subject to a recall or part of a manufacturer's replacement/upgrade program is included.</i>								
Device Type	Manufacturer	Model Number	Date	Qty				
Items listed for Recall or Replacement/Upgrade								
No items found during this inspection.								
Scan Number	Model	Type/Size	Discrepancy	Solution	Cost	A P P R O V E D	F I X E D	Date Corrected and Passed Retest
Emergency Light, Combination								
A0248213		Combination	Failed Test NFPA101 7.9.2.1	Req. x1 6V5AH	T/M	☐	☐	

Location: 1st Living Room Exit above door by tv (BC on doorframe) **Note:**

Extinguisher Cabinet								
A0245450			Damaged/Worn NFPA10 7.2.3	See Device Note	T/M	☐	☐	

Location: 1st At Rear Exit **Note:** Plexiglass panel broken, replacement required.
Attached x3 pictures of cabinet with approximate dimensions via "Measure" app.

Total Cost (excluding taxes): T/M
Customer WO/PO #: (none)
Internal WO/PO #: (none)

Inspection & Testing

Generated by: BuildingReports.ca

Building: Kerry's Place				
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed /Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	ScanID : S/N	Service	Date Time
Passed				
Fire				
Fire Extinguisher, 10 Lbs, A.B.C.	Basement	A0248214	Inspected	10/21/25 10:57:27 AM
Fire Extinguisher, 10 Lbs, A.B.C.	1st At Entrance	A0248209 E77570572	Inspected	10/21/25 11:05:54 AM
Fire Extinguisher, 5 Lbs, A.B.C.	1st At Rear Exit	A0248216 H29019695	Inspected	10/21/25 11:07:20 AM
Fire Extinguisher, 10 Lbs, A.B.C.	1st Attic Stairs	A0248215 ZN-753125	Inspected	10/21/25 10:49:24 AM
Lighting				
Emergency Light, Combination	1st At Entrance (BC on doorframe)	A0245451	Inspected	10/21/25 11:01:06 AM
Emergency Light, Combination	1st At Rear Exit	A0248217	Inspected	10/21/25 10:59:37 AM
Failed/Other				
Fire				
Extinguisher Cabinet, Hammer:	1st At Rear Exit	A0245450	Inspected	10/21/25 11:09:13 AM
Lighting				
Emergency Light, Combination	1st Living Room Exit above door by tv (BC on doorframe)	A0248213	Inspected	10/21/25 11:19:24 AM

Exit/Emergency Lighting

Generated by: BuildingReports.ca

Building: Kerry's Place								
<i>Exit and Emergency Lighting items are listed with each of the relevant measurements for pre and post test voltages, the load current, charge rate, and the rated voltage and current capacity of standby batteries. The remote heads indicate the number of other items that get their supply voltage from this item. Items are listed by type, and grouped by Passed or Failed /Other.</i>								
Location	Model #	Rated Volts	Pre-Test Volts	Post-Test Volts	Load Amps	Charge Amps	Remote Heads	Amp Hours
Passed								
Emergency Light, Combination								
1st At Rear Exit		6						5
1st At Entrance (BC on doorframe)		6						5
Failed/Other								
Emergency Light, Combination								
1st Living Room Exit above door by tv (BC on doorframe)		6						5

Sprinkler Inspection Certificate

For


Kerry's Place

Building Number: 1543572

This Inspection was performed in accordance with applicable standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

The devices in this report are 100% tested and 100% passed

*Annual Inspection
Inspection Date
Oct 23, 2025*



Building: Kerry's Place
Contact: MAIN .

Company: Georgian Bay Fire & Safety - Peterborough
Contact: Brad Forbes

To obtain further details about this inspection please utilize your login and password to view online.
This SprinklerScan report should be accompanied with the associated BRForm.

Sprinkler Inspection Report

Executive Summary

Generated by: BuildingReports.ca

Building Information

Building: Kerry's Place

Contact: MAIN .

Address:

Phone: .

Address:

City/Province/Postal Code:

Email: accountspayable@kerrysplace.org

Inspection Performed By

Company: Georgian Bay Fire & Safety - Peterborough

Inspector: Brad Forbes

Address: 347 Pido Road

Phone: .

Address: Unit 19

City/Province/Postal Code: Peterborough, Ontario K9J 6X7

Email: bforbes@gbfire.com

System Control Unit

System Type	System Location	Protected Area	Devices
Wet Pipe	Basement	Pump controller	1
Wet Pipe	Basement	Pump discharge	1
Wet Pipe	Basement	Pump suction	1

Inspection Summary

Category:	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Pump	1	33.33%	1	100.00%	1	100.00%	0	0.00%
Valve	2	66.67%	2	100.00%	2	100.00%	0	0.00%
Totals	3	100%	3	100.00%	3	100.00%	0	0.00%


Certification

Company: Georgian Bay Fire & Safety - Peterborough

Building: Kerry's Place

Inspector: Brad Forbes

Contact: MAIN .



Signed: Oct 23, 2025

Signed:

Notes & Recommendations

Generated by: BuildingReports.ca

Building: Kerry's Place				
<i>The Notes & Recommendations Report details notes made by the technician during the course of the building inspection for passed devices and the inspection as a whole.</i>				
Note	Device Type	Location	Comment	ScanID
Basement Wet Pipe, Pump controller				
1	Pump	Basement pump	Passed	98314151
Pump on at 40psi off at 80. Residual pressure 46. Bell on controller rings while pump is running . Manual shut off				
Basement Wet Pipe, Pump discharge				
2	Control Valve	Pump discharge	Passed	98314150
Handle removed to prevent tampering				

Inspection & Testing

Generated by: BuildingReports.ca

Building: Kerry's Place

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Basement Wet Pipe, Pump controller				
Pump	Basement pump	Annual	9:44:31 AM	10/23/2025
Basement Wet Pipe, Pump discharge				
Control Valve	Pump discharge	Annual	9:45:18 AM	10/23/2025
Basement Wet Pipe, Pump suction				
Control Valve	Pump suction	Annual	9:46:49 AM	10/23/2025

Wet Pipe Fire Sprinkler Systems

Generated by: BuildingReports.ca

Building: Kerry's Place				Basement, Pump controller		
<i>This section lists out all the devices and components that have been associated with a Wet Pipe System and provides details as to type of component, pressure readings, response time, etc. If a component has an OK checkbox that is checked, then that component was tested and passed; however, if the OK checkbox is unchecked, refer to the Inspection & Testing section for test status.</i>						
Pump						
Manufacturer	Model #	Location	Serial #	Install Date	OK	ScanID
Tornatech	RPA1-240/1.5/1 /60	Basement pump		10/29/2019	☒	98314151
Type	Orientation	Aligned?	Water Supply	Impeller Size	Startup	
Pump Primary	Vertical In-Line				Automatic	
Building: Kerry's Place				Basement, Pump discharge		
<i>This section lists out all the devices and components that have been associated with a Wet Pipe System and provides details as to type of component, pressure readings, response time, etc. If a component has an OK checkbox that is checked, then that component was tested and passed; however, if the OK checkbox is unchecked, refer to the Inspection & Testing section for test status.</i>						
Components						
Control Valve						
Type	Location	Manufacturer	Model #	OK	ScanID	
Ball	Pump discharge			☒	98314150	
Position	Size	Status	Description			
Open	1.25"	Sealed	Discharge			
Building: Kerry's Place				Basement, Pump suction		
<i>This section lists out all the devices and components that have been associated with a Wet Pipe System and provides details as to type of component, pressure readings, response time, etc. If a component has an OK checkbox that is checked, then that component was tested and passed; however, if the OK checkbox is unchecked, refer to the Inspection & Testing section for test status.</i>						
Control Valve						
Type	Location	Manufacturer	Model #	OK	ScanID	
Ball	Pump suction			☒	98314152	
Position	Size	Status	Description			
Open	1.25"	Sealed	Discharge			

Inspection Information:

- 1.OB/Contract NO:
- 2.Building Name:
- 3.Address:
- 4.Date Completed: **10/23/25**

Main Drain Flow Test:

- 1.Water Supply Source:
 - ☐ City
 - ☐ Pump
 - ☒ Tank
- 2.Drain Size: **1"**
- 3.Static Pressure: (PSI) **81**
- 4.Residual Pressure: (PSI) **46**
- 5.Did the floor drain take the water flow?
 - ☐ Yes
 - ☐ No
 - ☒ N/A
 - ☐ See Remarks

Alarm Test

- 1.Were all the inspector's test valves opened and flowed?
 - ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
- 2.Did the alarm valve(s) function properly?
 - ☐ Yes
 - ☐ No
 - ☒ N/A
 - ☐ See Remarks
- 3.Did the alarm line check valves (multi-headers) work?
 - ☐ Yes
 - ☐ No
 - ☒ N/A
 - ☐ See Remarks
- 4.Did the water motor gong function properly?
 - ☐ Yes
 - ☐ No
 - ☒ N/A
 - ☐ See Remarks
- 5.Did the 120vac bell(s) function properly?
 - ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
- 6.Did all flow switches register correctly at the fire alarm/monitoring panel?
 - ☐ Yes
 - ☐ No
 - ☒ N/A
 - ☐ See Remarks
- 7.Did the alarm line switch register correctly at the fire alarm/monitoring panel?
 - ☐ Yes
 - ☐ No
 - ☒ N/A
 - ☐ See Remarks
- 8.Were flow alarms received and properly identified by the monitoring station?
 - ☐ Yes
 - ☐ No
 - ☒ N/A
 - ☐ See Remarks
- 9.How many flow switches were tested? **None**

Supplementary Information:

- 1.Is the entrance to the sprinkler room and the area surrounding the main riser(s) adequately cleared?
 - ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
- 2.Is the sprinkler room and all areas with sprinkler piping adequately heated?

- ☒ Yes
- ☐ No
- ☐ N/A
- ☐ See Remarks

3. Were the pump valves left in the appropriate positions?

- ☒ Yes
- ☐ No
- ☐ N/A
- ☐ See Remarks

4. Were the alarm line shutoff valves left open?

- ☐ Yes
- ☐ No
- ☒ N/A
- ☐ See Remarks

5. Were all the main control valves left open?

- ☒ Yes
- ☐ No
- ☐ N/A
- ☐ See Remarks

6. Was the fire alarm/monitoring panel left clear of all flow alarms and supervisory conditions?

- ☐ Yes
- ☐ No
- ☒ N/A
- ☐ See Remarks

7. Does the backflow preventer require annual testing?

- ☐ Yes
- ☐ No
- ☒ N/A
- ☐ See Remarks

8. Does the excess pressure pump function properly?

- ☐ Yes
- ☐ No
- ☒ N/A

9. Manual or Automatic?

- ☐ Manual
- ☐ Automatic
- ☒ N/A

10. PSI the system pressure was left at: **81**

Supervisory Tests

1. Are all the main control valves indicating type?

- ☒ Yes
- ☐ No
- ☐ N/A
- ☐ See Remarks

2. Are all the main control valves in good working order?

- ☒ Yes
- ☐ No
- ☐ N/A
- ☐ See Remarks

3. Were all main control valves sealed or supervised?

- ☒ Yes
- ☐ No
- ☐ N/A
- ☐ See Remarks

4. Were valve supervision tests satisfactory?

- ☐ Yes
- ☐ No
- ☒ N/A
- ☐ See Remarks

5. Were the low pressure supervision tests satisfactory?

- ☐ Yes
- ☐ No
- ☒ N/A
- ☐ See Remarks

6. Do all the supervisory functions register correctly at the fire alarm/monitoring panel?

- ☐ Yes
- ☐ No

- ☒ N/A
 - ☐ See Remarks
7. Were supervisory functions received and properly identified by the monitoring station?
- ☐ Yes
 - ☐ No
 - ☒ N/A
 - ☐ See Remarks

Sprinkler and Piping

1. Do the sprinkler heads/concealed head plates appear to be free of paint, corrosion, physical damage or obstructions?
- ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
2. Is there a minimum clearance of 18" maintained below the sprinkler head?
- ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
3. Are the sprinkler heads less than 50 years old?
- ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
4. Are the sprinkler temperature ratings adequate in areas of high ambient heat?
- ☐ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
5. Does the sprinkler piping and pipe hangers appear to be secure and in good condition?
- ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
6. Is there an adequate supply of spare sprinkler heads and a head wrench in the appropriate cabinet?
- ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
7. Do the sprinkler heads appear to be properly spaced?
- ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
8. Do the sprinkler heads appear to be proper types as per orientation?
- ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks

FIRE DEPARTMENT CONNECTION (SIAMESE)

1. Are the connections accessible, visible and free of obstructions?
- ☐ Yes
 - ☐ No
 - ☒ N/A
 - ☐ See Remarks
2. Are caps/plugs in place and do the couplings turn freely?
- ☐ Yes
 - ☐ No
 - ☒ N/A
 - ☐ See Remarks
3. Is the check valve tight and the ball drip functioning?
- ☐ Yes
 - ☐ No
 - ☒ N/A
 - ☐ See Remarks

GARBAGE CHUTE

1. Is the fusible link clean and in good condition?

- ☐ Yes
- ☐ No
- ☒ N/A
- ☐ See Remarks

2. Is the garbage chute protected with sprinkler head?

- ☐ Pass
- ☐ No
- ☒ N/A
- ☐ See Remarks

Glycol Loops

Glycol Loops			
Loop Location:	Pipe Size:	Number of Heads:	Freezing Point:
.	.	.	.


ALARM VALVE/RISER INFORMATION:

ALARM VALVE/RISER INFORMATION:					
System:	Size:	Make and Model:	System Pressure:	Location:	Location of Test Valve:
Wet	1.25"	Pump and tank	81	Basement	At riser into tank

Remarks

1. REMARKS: NA

2. Technician Signature:



Signed on 10/23/25 9:59:06 AM

3. Status of Inspection



Pass