

Fire Alarm and Life Safety System Inspection Certificate

For

Kerry's Place

Building Number: 1543579

Tested to CAN/ULC S536-04 Standard
Smoke alarms are inspected to CAN ULC S553-02

This report should be accompanied by the BRForm containing the contents of CAN/ULC S536-04 Appendix E

This Inspection was performed in accordance with applicable ULC Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.


The devices in this report are 100% tested and 100% passed

Annual Inspection

Start Date: Oct 22, 2025

End Date: Oct 22, 2025

Service - Tested



Building: Kerry's Place
Contact: MAIN .



Company: Georgian Bay Fire & Safety - Peterborough
Contact: Derek Rennie

To obtain further details about this inspection please utilize your login and password to view online.
This FireScan report should be accompanied with the associated BRForm.

Fire Alarm Testing Report

Executive Summary

Generated by: BuildingReports.ca

Building Information

Building: Kerry's Place

Contact: MAIN .

Address:

Phone: .

Address:

City/Province/Postal Code:

Email: accountspayable@kerrysplace.org

Inspection Performed By

Company: Georgian Bay Fire & Safety - Peterborough

Inspector: Derek Rennie

Address: 347 Pido Road

Phone: 1-800-265-3197

Address: Unit 19

City/Province/Postal Code: Peterborough, Ontario K9J 6X7

Email: derek.rennie@fire-sp.com


Certification

Company: Georgian Bay Fire & Safety - Peterborough


Building: Kerry's Place

Inspector: Derek Rennie

Contact: MAIN .



Signed: Oct 22, 2025



Signed: Oct 22, 2025

Individual Device Record

Generated by: BuildingReports.ca

Type of Inspection: Fire Alarm System Annual Inspection and Test (ULC S536-04)

Building Name: Kerry's Place

Inspection Date and Time: 10/22/25 12:58:56 PM

Inspector: Derek Rennie

Note: The Location Column includes the location, time and date of the inspection and barcode number.

Remarks Column: Detector sensitivity in percentage and Waterflow Switch time delay in seconds.

For specific output circuit operation confirmation see associated BRForm section - "Ancillary Function Testing"

Location	Device Type	Correctly Installed	Requires Service, Repairs, Cleaning or Missing	Alarm Operation Confirmed	Annunciation Indication Confirmed	Zone Circuit Number or Address	Supervision of Wiring Device Confirmed	Ground Circuit Confirmed	Remarks/ Readings
Tested									
Basement At Bedrooms, 12:45:00PM 10/22/2025 (A0248323)	Smoke Alarm	☒	☐	☐	☐	1- Interconnected	☐	☐	LTD 10/22 /2025
Basement Bedroom North/West, 12:47:05PM 10/22/2025 (A0248325)	Smoke Alarm	☒	☐	☐	☐	1- Interconnected	☐	☐	LTD 10/22 /2025
Basement Bedroom South/West, 12:46:11PM 10/22/2025 (A0248324)	Smoke Alarm	☒	☐	☐	☐	1- Interconnected	☐	☐	LTD 10/22 /2025
Basement Furnace Room, 12:48:13PM 10/22/2025 (A0248333)	CO Alarm	☐	☐	☐	☐	1	☐	☐	LTD 10/22 /2025
Basement Furnace Room, 12:52:31PM 10/22/2025 (A0245447)	Smoke Alarm	☒	☐	☐	☐	1- Interconnected	☐	☐	LTD 10/22 /2025
Basement Kitchenette, 12:43:24PM 10/22/2025 (A0248322)	Smoke Alarm	☒	☐	☐	☐	1- Interconnected	☐	☐	LTD 10/22 /2025
1st Bedroom#1 East, 12:58:56PM 10/22/2025 (A0248320)	Smoke Alarm	☒	☐	☐	☐	1- Interconnected	☐	☐	LTD 10/22 /2025
1st Bedroom#1 South, 12:56:29PM 10/22/2025 (A0248318)	Smoke Alarm	☒	☐	☐	☐	1- Interconnected	☐	☐	LTD 10/22 /2025
1st Hallway, 12:54:23PM 10/22/2025 (A0248321)	Smoke Alarm	☒	☐	☐	☐	1- Interconnected	☐	☐	LTD 10/22 /2025
1st Office, 12:57:45PM 10/22/2025 (A0248319)	Smoke Alarm	☒	☐	☐	☐	1- Interconnected	☐	☐	LTD 10/22 /2025

Inspection & Testing

Generated by: BuildingReports.ca

Building: Kerry's Place			Control Panel: 1	
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
<i>Passed</i>				
Initiating				
CO Alarm	Basement Furnace Room	Tested	12:48:13 PM	10/22/2025
Smoke Alarm	Basement At Bedrooms	Tested	12:45:00 PM	10/22/2025
Smoke Alarm	Basement Bedroom North/West	Tested	12:47:05 PM	10/22/2025
Smoke Alarm	Basement Bedroom South/West	Tested	12:46:11 PM	10/22/2025
Smoke Alarm	Basement Furnace Room	Tested	12:52:31 PM	10/22/2025
Smoke Alarm	Basement Kitchenette	Tested	12:43:24 PM	10/22/2025
Smoke Alarm	1st Bedroom#1 East	Tested	12:58:56 PM	10/22/2025
Smoke Alarm	1st Bedroom#1 South	Tested	12:56:29 PM	10/22/2025
Smoke Alarm	1st Hallway	Tested	12:54:23 PM	10/22/2025
Smoke Alarm	1st Office	Tested	12:57:45 PM	10/22/2025

Smoke Alarms

Generated by: BuildingReports.ca

Building: Kerry's Place				
The smoke alarm report details the inspection of smoke alarms.				
Scan ID	Location	Type	Voltage	Mfr. Date
Passed				
A0248323	Basement At Bedrooms	Combo SA/CO	110V/Bat	10/31/2021
A0248325	Basement Bedroom North/West	Ionization	110V/Bat	10/31/2023
A0248324	Basement Bedroom South/West	Ionization	110V/Bat	10/31/2023
A0245447	Basement Furnace Room	Ionization	110V/Bat	10/31/2023
A0248322	Basement Kitchenette	Ionization	110V/Bat	10/31/2023
A0248320	1st Bedroom#1 East	Ionization	110V/Bat	10/31/2023
A0248318	1st Bedroom#1 South	Ionization	110V/Bat	10/31/2023
A0248321	1st Hallway	Combo SA/CO	110V/Bat	10/31/2019
A0248319	1st Office	Ionization	110V/Bat	10/31/2023

Inventory & Warranty Report

Generated by: BuildingReports.ca

Building: Kerry's Place				Control Panel: 1
<i>The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i>				
Device or Type		Category	% of Inventory	Quantity
CO Alarm		Initiating	10.00%	1
Smoke Alarm		Initiating	90.00%	9
Type	Qty	Model #	Description	Install Date
<i>In Service - 90 Days - 1 Year</i>				
Kidde				
Smoke Alarm	1	i12040ACA	Ionization	11/29/2024
<i>In Service - 1 Year to 2 Years</i>				
First Alert				
CO Alarm	1	GCO1A	CO	10/31/2023
Kidde				
Smoke Alarm	6	i12060ACA	Ionization	10/31/2023
<i>In Service - 3 Years to 5 Years</i>				
Kidde				
Smoke Alarm	1	KN-COPE-ICCA	Combo SA/CO	10/31/2021
<i>In Service - 5 Years to 10 Years</i>				
Kidde				
Smoke Alarm	1	KN-COPE-ICCA	Combo SA/CO	10/31/2019

Safety Equipment Inspection Report

For


Kerry's Place

Building Number: 1543579

This Inspection was performed in accordance with applicable standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

The devices in this report are 100% tested and 83% passed

*Annual Inspection
Inspection Date
Oct 22, 2025*



Building: Kerry's Place
Contact: MAIN .



Company: Georgian Bay Fire & Safety - Peterborough
Contact: Derek Rennie
Safety Equipment Report

Executive Summary

Generated by: BuildingReports.ca

Building Information

Building: Kerry's Place

Contact: MAIN .

Address:

Phone: .

Address:

City/Province/Postal Code:

Email: accountspayable@kerrysplace.org

Inspection Performed By

Company: Georgian Bay Fire & Safety - Peterborough

Inspector: Derek Rennie

Address: 347 Pido Road

Phone: 1-800-265-3197

Address: Unit 19

City/Province/Postal Code: Peterborough, Ontario K9J 6X7

Email: derek.rennie@fire-sp.com

Inspection Summary

Category:	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Fire	5	83.33%	5	100.00%	5	100.00%	0	0.00%
Lighting	1	16.67%	1	100.00%	0	0.00%	1	100.00%
Totals	6	100%	6	100.00%	5	83.33%	1	16.67%

Certification

Company: Georgian Bay Fire & Safety - Peterborough


Building: Kerry's Place

Inspector: Derek Rennie

Contact: MAIN .



Signed: Oct 22, 2025



Signed: Oct 22, 2025

Discrepancy Report with Proposed Solutions

Generated by: BuildingReports.ca

Building: Kerry's Place								
<i>This report consolidates all discrepancies and provides proposed solutions to these issues. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any devices that have been corrected and passed the retest are checkmarked under the Fixed column and details regarding the individual who completed the fix are noted in the last column. Any item that was inspected that is subject to a recall or part of a manufacturer's replacement/upgrade program is included.</i>								
Device Type		Manufacturer		Model Number		Date		Qty
Items listed for Recall or Replacement/Upgrade								
No items found during this inspection.								
						A P P R O V E D	F I X E D	Date Corrected and Passed Retest
Scan Number	Model	Type/Size	Discrepancy	Solution	Cost			
Emergency Light, Power Unit								
A0248326	RG36	Power Unit	Failed Test NFPA101 7.9.2.1	Req. x1 6V7AH	T/M	☐	☐	
Location: 1st At Kitchen			Note:					

Total Cost (excluding taxes): T/M

Customer WO/PO #: (none)

Internal WO/PO #: (none)

Inspection & Testing

Generated by: BuildingReports.ca

Building: Kerry's Place

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed /Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	ScanID : S/N	Service	Date Time
<i>Passed</i>				
Fire				
Fire Extinguisher, 10 Lbs, A.B.C.	Basement At Kitchenette	A0248328 I32559544	Inspected	10/22/25 1:01:03 PM
Fire Extinguisher, 10 Lbs, A.B.C.	Basement At Patio Exit	A0248330 I32559558	Inspected	10/22/25 1:02:11 PM
Fire Extinguisher, 10 Lbs, A.B.C.	Basement Furnace room	A0248331 H88935942	Inspected	10/22/25 1:03:12 PM
Fire Extinguisher, 10 Lbs, A.B.C.	1st At Entrance	A0248329 I32559567	Inspected	10/22/25 1:07:36 PM
Fire Extinguisher, 10 Lbs, A.B.C.	1st At Kitchen	A0248327 I32559550	Inspected	10/22/25 1:08:12 PM
<i>Failed/Other</i>				
Lighting				
Emergency Light, Power Unit	1st At Kitchen	A0248326	Inspected	10/22/25 1:29:11 PM

Exit/Emergency Lighting

Generated by: BuildingReports.ca

Building: Kerry's Place

Exit and Emergency Lighting items are listed with each of the relevant measurements for pre and post test voltages, the load current, charge rate, and the rated voltage and current capacity of standby batteries. The remote heads indicate the number of other items that get their supply voltage from this item. Items are listed by type, and grouped by Passed or Failed /Other.

Location	Model #	Rated Volts	Pre-Test Volts	Post-Test Volts	Load Amps	Charge Amps	Remote Heads	Amp Hours
Failed/Other								
Emergency Light, Power Unit								
1st At Kitchen	RG36	6					2	7

Sprinkler Inspection Report

For


Kerry's Place

Building Number: 1543579

This Inspection was performed in accordance with applicable standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

The devices in this report are 100% tested and 75% passed

*Annual Inspection
Inspection Date
Oct 22, 2025*



Building: Kerry's Place
Contact: MAIN .

Company: Georgian Bay Fire & Safety - Peterborough
Contact: Brad Forbes

To obtain further details about this inspection please utilize your login and password to view online.
This SprinklerScan report should be accompanied with the associated BRForm.

Sprinkler Inspection Report

Executive Summary

Generated by: BuildingReports.ca

Building Information

Building: Kerry's Place

Contact: MAIN .

Address:

Phone: .

Address:

City/Province/Postal Code:

Email: accountspayable@kerrysplace.org

Inspection Performed By

Company: Georgian Bay Fire & Safety - Peterborough

Inspector: Brad Forbes

Address: 347 Pido Road

Phone: .

Address: Unit 19

City/Province/Postal Code: Peterborough, Ontario K9J 6X7

Email: bforbes@gbfire.com

System Control Unit

System Type	System Location	Protected Area	Devices
Wet Pipe	Furnace rm	BFP in	1
Wet Pipe	Furnace rm	BFP out	1
Wet Pipe	Furnace rm	Flow	2

Inspection Summary

Category:	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Alarm	1	25.00%	1	100.00%	1	100.00%	0	0.00%
Device	1	25.00%	1	100.00%	0	0.00%	1	100.00%
Valve	2	50.00%	2	100.00%	2	100.00%	0	0.00%
Totals	4	100%	4	100.00%	3	75.00%	1	25.00%


Certification

Company: Georgian Bay Fire & Safety - Peterborough

Building: Kerry's Place

Inspector: Brad Forbes

Contact: MAIN .



Signed: Oct 22, 2025

Signed:

Discrepancy Report with Proposed Solutions

Generated by: BuildingReports.ca

Building: Kerry's Place

This report consolidates all discrepancies and provides proposed solutions to these issues. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any devices that have been corrected and passed the retest are checkmarked under the Fixed column and details regarding the individual who completed the fix are noted in the last column. Any item that was inspected that is subject to a recall or part of a manufacturer's replacement/upgrade program is included.

Device Type	Manufacturer	Model Number	Date	Qty				
Items listed for Recall or Replacement/Upgrade								
No items found during this inspection.								
Scan Number	Model	Type/Size	Discrepancy	Solution	Cost	A	F	Date Corrected and Passed Retest
						P		
						P		
						R		
						O		
V	E	D						
System Documents								
0000001	DCLF4A		Date Expired	Test BFP	T/M	☐	☐	
Location: Backflow preventer				Note: Backflow preventer has not been tagged as tested since 2019				

Total Cost (excluding taxes): T/M

Customer WO/PO #: (none)

Internal WO/PO #: (none)

Inspection & Testing

Generated by: BuildingReports.ca

Building: Kerry's Place				
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	Service	Time	Date
<i>Passed</i>				
Furnace rm Wet Pipe, BFP in				
Control Valve	BFP in	Annual	12:52:41 PM	10/22/2025
Furnace rm Wet Pipe, BFP out				
Control Valve	BFP out	Annual	12:52:53 PM	10/22/2025
Furnace rm Wet Pipe, Flow				
Waterflow Switch	Flow	Annual	12:53:03 PM	10/22/2025
<i>Failed/Other</i>				
Furnace rm Wet Pipe, Flow				
System Documents	Backflow preventer	Tested	1:05:37 PM	10/22/2025

Wet Pipe Fire Sprinkler Systems

Generated by: BuildingReports.ca

Building: Kerry's Place				Furnace rm, BFP in		
<i>This section lists out all the devices and components that have been associated with a Wet Pipe System and provides details as to type of component, pressure readings, response time, etc. If a component has an OK checkbox that is checked, then that component was tested and passed; however, if the OK checkbox is unchecked, refer to the Inspection & Testing section for test status.</i>						
Components						
Control Valve						
Type	Location	Manufacturer	Model #	OK	ScanID	
Butterfly	BFP in	Victaulic	702	☒	98313901	
Position	Size	Status	Description			
Open	2"	Supervised	Main Control			
Building: Kerry's Place				Furnace rm, BFP out		
<i>This section lists out all the devices and components that have been associated with a Wet Pipe System and provides details as to type of component, pressure readings, response time, etc. If a component has an OK checkbox that is checked, then that component was tested and passed; however, if the OK checkbox is unchecked, refer to the Inspection & Testing section for test status.</i>						
Control Valve						
Type	Location	Manufacturer	Model #	OK	ScanID	
Butterfly	BFP out	Victaulic	702	☒	98313902	
Position	Size	Status	Description			
Open	2"	Supervised	Main Control			
Building: Kerry's Place				Furnace rm, Flow		
<i>This section lists out all the devices and components that have been associated with a Wet Pipe System and provides details as to type of component, pressure readings, response time, etc. If a component has an OK checkbox that is checked, then that component was tested and passed; however, if the OK checkbox is unchecked, refer to the Inspection & Testing section for test status.</i>						
Alarms						
Waterflow Switch						
Type	Manufacturer	Model #	Sec	Size	Zone/Address	OK ScanID
Vane	System Sensor	WFD20NA	32.4500007629395	2"	1-1	☒ 98313903
Devices						

Inspection Information:

- 1.OB/Contract NO:
- 2.Building Name:
- 3.Address:
- 4.Date Completed: 10/22/25

Main Drain Flow Test:

- 1.Water Supply Source:
 - ☒ City
 - ☐ Pump
 - ☐ Tank
- 2.Drain Size: 1"
- 3.Static Pressure: (PSI) 60
- 4.Residual Pressure: (PSI) 48
- 5.Did the floor drain take the water flow?
 - ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks

Alarm Test

- 1.Were all the inspector's test valves opened and flowed?
 - ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
- 2.Did the alarm valve(s) function properly?
 - ☐ Yes
 - ☐ No
 - ☒ N/A
 - ☐ See Remarks
- 3.Did the alarm line check valves (multi-headers) work?
 - ☐ Yes
 - ☐ No
 - ☒ N/A
 - ☐ See Remarks
- 4.Did the water motor gong function properly?
 - ☐ Yes
 - ☐ No
 - ☒ N/A
 - ☐ See Remarks
- 5.Did the 120vac bell(s) function properly?
 - ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
- 6.Did all flow switches register correctly at the fire alarm/monitoring panel?
 - ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
- 7.Did the alarm line switch register correctly at the fire alarm/monitoring panel?
 - ☐ Yes
 - ☐ No
 - ☒ N/A
 - ☐ See Remarks
- 8.Were flow alarms received and properly identified by the monitoring station?
 - ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
- 9.How many flow switches were tested? 1

Supplementary Information:

- 1.Is the entrance to the sprinkler room and the area surrounding the main riser(s) adequately cleared?
 - ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
- 2.Is the sprinkler room and all areas with sprinkler piping adequately heated?

- ☒ Yes
- ☐ No
- ☐ N/A
- ☐ See Remarks

3. Were the pump valves left in the appropriate positions?

- ☐ Yes
- ☐ No
- ☒ N/A
- ☐ See Remarks

4. Were the alarm line shutoff valves left open?

- ☐ Yes
- ☐ No
- ☒ N/A
- ☐ See Remarks

5. Were all the main control valves left open?

- ☒ Yes
- ☐ No
- ☐ N/A
- ☐ See Remarks

6. Was the fire alarm/monitoring panel left clear of all flow alarms and supervisory conditions?

- ☒ Yes
- ☐ No
- ☐ N/A
- ☐ See Remarks

7. Does the backflow preventer require annual testing?

- ☒ Yes
- ☐ No
- ☐ N/A
- ☐ See Remarks

8. Does the excess pressure pump function properly?

- ☐ Yes
- ☐ No
- ☒ N/A

9. Manual or Automatic?

- ☐ Manual
- ☐ Automatic
- ☒ N/A

10. PSI the system pressure was left at: **60**

Supervisory Tests

1. Are all the main control valves indicating type?

- ☒ Yes
- ☐ No
- ☐ N/A
- ☐ See Remarks

2. Are all the main control valves in good working order?

- ☒ Yes
- ☐ No
- ☐ N/A
- ☐ See Remarks

3. Were all main control valves sealed or supervised?

- ☒ Yes
- ☐ No
- ☐ N/A
- ☐ See Remarks

4. Were valve supervision tests satisfactory?

- ☒ Yes
- ☐ No
- ☐ N/A
- ☐ See Remarks

5. Were the low pressure supervision tests satisfactory?

- ☐ Yes
- ☐ No
- ☒ N/A
- ☐ See Remarks

6. Do all the supervisory functions register correctly at the fire alarm/monitoring panel?

- ☒ Yes
- ☐ No

- ☐ N/A
 - ☐ See Remarks
7. Were supervisory functions received and properly identified by the monitoring station?
- ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks

Sprinkler and Piping

1. Do the sprinkler heads/concealed head plates appear to be free of paint, corrosion, physical damage or obstructions?
- ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
2. Is there a minimum clearance of 18" maintained below the sprinkler head?
- ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
3. Are the sprinkler heads less than 50 years old?
- ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
4. Are the sprinkler temperature ratings adequate in areas of high ambient heat?
- ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
5. Does the sprinkler piping and pipe hangers appear to be secure and in good condition?
- ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
6. Is there an adequate supply of spare sprinkler heads and a head wrench in the appropriate cabinet?
- ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
7. Do the sprinkler heads appear to be properly spaced?
- ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
8. Do the sprinkler heads appear to be proper types as per orientation?
- ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks

FIRE DEPARTMENT CONNECTION (SIAMESE)

1. Are the connections accessible, visible and free of obstructions?
- ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
2. Are caps/plugs in place and do the couplings turn freely?
- ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks
3. Is the check valve tight and the ball drip functioning?
- ☒ Yes
 - ☐ No
 - ☐ N/A
 - ☐ See Remarks

GARBAGE CHUTE

1. Is the fusible link clean and in good condition?

- ☐ Yes
☐ No
☒ N/A
☐ See Remarks

2. Is the garbage chute protected with sprinkler head?

- ☐ Pass
☐ No
☒ N/A
☐ See Remarks

Glycol Loops

Glycol Loops			
Loop Location:	Pipe Size:	Number of Heads:	Freezing Point:
.	.	.	.


ALARM VALVE/RISER INFORMATION:

ALARM VALVE/RISER INFORMATION:					
System:	Size:	Make and Model:	System Pressure:	Location:	Location of Test Valve:
Wet	2"	Shotgun riser	60	Furnace Rm	At riser

Remarks

1. REMARKS: Backflow preventer has not been tested

2. Technician Signature:



Signed on 10/22/25 1:02:13 PM

3. Status of Inspection