

Safety Equipment Inspection Certificate

For

Kerry's Place Autism Services

Building Number: 1035925

This Inspection was performed in accordance with applicable standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

The devices in this report are 100% tested and 100% passed

*Annual Inspection
Inspection Date
Dec 9, 2025*

Building: Kerry's Place Autism Services
Contact: Nikolas Dzambas

Company: D & L Fire Protection Limited
Contact: Blake Usiski

Safety Equipment Report

Executive Summary

Generated by: BuildingReports.ca

Building Information								
Building: Kerry's Place Autism Services				Contact: Nikolas Dzambas				
Address:				Phone: 905-841-6611				
Address:				City/Province/Postal Code:				
Email: nikolas.Dzambas@kerrysplace.org								
Inspection Performed By								
Company: D & L Fire Protection Limited				Inspector: Blake Usiski				
Address: 320 Harry Walker Pkwy N. #15				Phone: 905 898 6204				
Address:				City/Province/Postal Code: Newmarket, Ontario L3Y7B4				
Email: dlfire@rogers.com								
Inspection Summary								
Category:	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Fire	4	100.00%	4	100.00%	4	100.00%	0	0.00%
Totals	4	100%	4	100.00%	4	100.00%	0	0.00%
Certification								
Company: D & L Fire Protection Limited				Building: Kerry's Place Autism Services				
Inspector: Blake Usiski				Contact: Nikolas Dzambas				

Inspection & Testing

Generated by: BuildingReports.ca

Building: Kerry's Place Autism Services

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed /Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	ScanID : S/N	Service	Date Time
<i>Passed</i>				
Fire				
Fire Extinguisher, 5 Lbs, A.B.C.	Basement apt	36763270 039756	12yr Maintenance	12/09/25 1:05:44 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Basement Electric Room apt	36763280 639716	12yr Maintenance	12/09/25 1:09:09 PM
Fire Extinguisher, 5 Lbs, A.B.C.	1st kitchen	36763291 039732	12yr Maintenance	12/09/25 1:02:20 PM
Fire Extinguisher, 5 Lbs, A.B.C.	1st main entrance	57017094 647547	12yr Maintenance	12/09/25 12:59:09 PM

Sprinkler Inspection Certificate

For

Kerry's Place Autism Services

Building Number: 1035925

This Inspection was performed in accordance with applicable standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

The devices in this report are 100% tested and 100% passed

*Annual Inspection
Inspection Date
Dec 9, 2025*

Building: Kerry's Place Autism Services
Contact: Nikolas Dzambas

Company: D & L Fire Protection Limited
Contact: Jay Hammond

To obtain further details about this inspection please utilize your login and password to view online. This SprinklerScan report should be accompanied with the associated BRForm.

Sprinkler Inspection Report

Executive Summary

Generated by: BuildingReports.ca

Building Information								
Building: Kerry's Place Autism Services				Contact: Nikolas Dzambas				
Address:				Phone: 905-841-6611				
Address:				City/Province/Postal Code:				
Email: nikolas.Dzambas@kerrysplace.org								
Inspection Performed By								
Company: D & L Fire Protection Limited				Inspector: Jay Hammond				
Address: 320 Harry Walker Pkwy N. #15				Phone: 905 898 6204				
Address:				City/Province/Postal Code: Newmarket, Ontario L3Y7B4				
Email: dlfire@rogers.com								
Inspection Summary								
Category:	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Alarm	1	6.25%	1	100.00%	1	100.00%	0	0.00%
Device	8	50.00%	8	100.00%	8	100.00%	0	0.00%
Hose	1	6.25%	1	100.00%	1	100.00%	0	0.00%
Pump	1	6.25%	1	100.00%	1	100.00%	0	0.00%
Sprinkler	1	6.25%	1	100.00%	1	100.00%	0	0.00%
Valve	4	25.00%	4	100.00%	4	100.00%	0	0.00%
Totals	16	100%	16	100.00%	16	100.00%	0	0.00%
Certification								
Company: D & L Fire Protection Limited				Building: Kerry's Place Autism Services				
Inspector: Jay Hammond				Contact: Nikolas Dzambas				

Inspection & Testing

Generated by: BuildingReports.ca

Building: Kerry's Place Autism Services

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
Passed				
Waterflow Switch	Basement mechanical room	Annual	1:05:26 PM	12/09/2025
Electric Bell	1st top of bsmt stairs	Tested	1:05:19 PM	12/09/2025
Gauge	Basement mechanical room	Annual	1:03:58 PM	12/09/2025
Water Storage Tank	Basement mechanical room	Annual	1:01:57 PM	12/09/2025
Water Storage Tank	Basement mechanical room	Annual	1:02:15 PM	12/09/2025
Water Storage Tank	Basement mechanical room	Annual	1:02:18 PM	12/09/2025
Water Storage Tank	Basement mechanical room	Annual	1:02:21 PM	12/09/2025
Water Storage Tank	Basement mechanical room	Annual	1:02:23 PM	12/09/2025
Water Storage Tank	Basement mechanical room	Annual	1:02:25 PM	12/09/2025
Fire Dep't Connection	1st outside by garage	Annual	1:03:15 PM	12/09/2025
Excess Pressure Pump	Basement mechanical room	Annual	1:03:08 PM	12/09/2025
Sprinkler Box	Basement mechanical room	Annual	1:03:20 PM	12/09/2025
Control Valve	Basement mechanical room	Annual	1:03:30 PM	12/09/2025
Control Valve	Basement mechanical room	Annual	1:04:45 PM	12/09/2025
Control Valve	Basement mechanical room	Annual	1:05:10 PM	12/09/2025
Inspector's Test	Basement mechanical room	Annual	1:02:52 PM	12/09/2025