

Sprinkler Inspection Certificate

For

Kerry's Place Autism Services

Building Number: 603534

This Inspection was performed in accordance with applicable standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

The devices in this report are 100% tested and 100% passed

Annual Inspection

Inspection Date

Sep 4, 2024

Building: Kerry's Place Autism Services
Contact: Ashley Powell

Company: D & L Fire Protection Limited
Contact: Jay Hammond

To obtain further details about this inspection please utilize your login and password to view online. This SprinklerScan report should be accompanied with the associated BRForm.

Sprinkler Inspection Report

Executive Summary

Generated by: BuildingReports.ca

Building Information								
Building: Kerry's Place Autism Services				Contact: Ashley Powell				
Address:				Phone: 289-380-8159				
Address:				City/Province/Postal Code:				
Email: ashley.powell@kerrysplace.org								
Inspection Performed By								
Company: D & L Fire Protection Limited				Inspector: Jay Hammond				
Address: 320 Harry Walker Pkwy N. #15				Phone: 905 898 6204				
Address:				City/Province/Postal Code: Newmarket, Ontario L3Y7B4				
Email: dlfire@rogers.com								
Inspection Summary								
Category:	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Alarm	2	22.22%	2	100.00%	2	100.00%	0	0.00%
Device	2	22.22%	2	100.00%	2	100.00%	0	0.00%
Pump	1	11.11%	1	100.00%	1	100.00%	0	0.00%
Sprinkler	2	22.22%	2	100.00%	2	100.00%	0	0.00%
Valve	2	22.22%	2	100.00%	2	100.00%	0	0.00%
Totals	9	100%	9	100.00%	9	100.00%	0	0.00%
Certification								
Company: D & L Fire Protection Limited				Building: Kerry's Place Autism Services				
Inspector: Jay Hammond				Contact: Ashley Powell				

Inspection & Testing

Generated by: BuildingReports.ca

Building: Kerry's Place Autism Services

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pressure Switch		Annual	1:15:43 PM	09/04/2024
Waterflow Switch		Annual	1:16:08 PM	09/04/2024
Gauge		Annual	1:15:35 PM	09/04/2024
Water Storage Tank		Annual	1:16:18 PM	09/04/2024
Excess Pressure		Annual	1:16:05 PM	09/04/2024
Pump				
Sprinkler Box		Annual	1:14:57 PM	09/04/2024
Sprinkler Box		Annual	1:15:01 PM	09/04/2024
Spares				
Check Valve		Annual	1:15:48 PM	09/04/2024
Inspector's Test		Annual	1:15:56 PM	09/04/2024

Safety Equipment Inspection Certificate

For

Kerry's Place Autism Services

Building Number: 603534

This Inspection was performed in accordance with applicable standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

The devices in this report are 100% tested and 100% passed

*Annual Inspection
Inspection Date
Sep 3, 2024*

Building: Kerry's Place Autism Services
Contact: Ashley Powell

Company: D & L Fire Protection Limited
Contact: Jeffrey Gouveia

Safety Equipment Report

Executive Summary

Generated by: BuildingReports.ca

Building Information								
Building: Kerry's Place Autism Services				Contact: Ashley Powell				
Address:				Phone: 289-380-8159				
Address:				City/Province/Postal Code:				
Email: ashley.powell@kerrysplace.org								
Inspection Performed By								
Company: D & L Fire Protection Limited				Inspector: Jeffrey Gouveia				
Address: 320 Harry Walker Pkwy N. #15				Phone: 9059536702				
Address:				City/Province/Postal Code: Newmarket, Ontario L3Y7B4				
Email: dlfire@rogers.com								
Inspection Summary								
Category:	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Fire	11	84.62%	11	100.00%	11	100.00%	0	0.00%
Lighting	2	15.38%	2	100.00%	2	100.00%	0	0.00%
Totals	13	100%	13	100.00%	13	100.00%	0	0.00%
Certification								
Company: D & L Fire Protection Limited				Building: Kerry's Place Autism Services				
Inspector: Jeffrey Gouveia				Contact: Ashley Powell				
Jeffrey Gouveia Certifications								
Certification Type						Number		
CFAA Registered Technician						19-998875		
CFAA Trainee Technician						19-998875		

Inspection & Testing

Generated by: BuildingReports.ca

Building: Kerry's Place Autism Services				
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed /Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
Device Type	Location	ScanID : S/N	Service	Date Time
Passed				
Fire				
Fire Extinguisher, 5 Lbs, A.B.C.	Basement Laundry room	75688648 H10598326	Inspected	09/03/24 3:26:02 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Basement Sprinkler room	88649186 H10650302	Inspected	09/03/24 3:23:49 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Basement furnace Room	36769421 F687356	Inspected	09/03/24 3:22:13 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Basement kitchen	41527034 201270	Inspected	09/03/24 3:20:38 PM
Fire Extinguisher, 5 Lbs, A.B.C. 2A:10B:C	Basement laundry By laundry room	41527029 207793	Inspected	09/03/24 3:25:00 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Basement sprinkler room detergent room	75688650 B66783881	Inspected	09/03/24 3:27:12 PM
Fire Extinguisher, 5 Lbs, A.B.C.	1st by office	41527026 199405	Inspected	09/03/24 3:13:16 PM
Fire Extinguisher, 5 Lbs, A.B.C.	1st kitchen	41527004 vv720089	Inspected	09/03/24 3:15:25 PM
Fire Extinguisher, 5 Lbs, A.B.C.	1st kitchen	75688646 B66750319	Inspected	09/03/24 3:15:31 PM
Fire Extinguisher, 5 Lbs, A.B.C.	1st top of stairs	75688647 B77712374	Inspected	09/03/24 3:17:49 PM
Fire Extinguisher, 5 Lbs, A.B.C.	1st tv room	39286238 720416	6yr Maintenance	09/03/24 3:32:06 PM
Lighting				
Emergency Light, Power Unit	Basement electrical	41527032	Inspected	09/03/24 3:29:26 PM
Emergency Light, Power Unit	1st office	41527005	Inspected	09/03/24 3:16:31 PM

Fire Extinguisher Maintenance Report

Generated by: BuildingReports.ca

Building: Kerry's Place Autism Services

This report provides details on the Hydrostatic Test and Maintenance/Breakdown dates for fire extinguishers. Items that will need either of these services at any time in the next two years are displayed. Items are grouped together by year for budgeting purposes.

ScanID	Location	Serial #	Hydro	Breakdown	Mfr Date
Due in 2026					
Breakdown/Maintenance					
Fire Extinguisher, A.B.C., 5 Lbs					
41527026	1st by office	199405	07/31/20	12/20/14	12/20/08
41527034	Basement kitchen	201270	07/31/20	12/20/14	12/20/08
41527029	Basement laundry By laundry room	207793	07/31/20	12/20/14	12/20/08
Total Fire Extinguisher, A.B.C., 5 Lbs:					3

Exit/Emergency Lighting

Generated by: BuildingReports.ca

Building: Kerry's Place Autism Services

Exit and Emergency Lighting items are listed with each of the relevant measurements for pre and post test voltages, the load current, charge rate, and the rated voltage and current capacity of standby batteries. The remote heads indicate the number of other items that get their supply voltage from this item. Items are listed by type, and grouped by Passed or Failed /Other.

Location	Model #	Rated Volts	Pre-Test Volts	Post-Test Volts	Load Amps	Charge Amps	Remote Heads	Amp Hours
<i>Passed</i>								
Emergency Light, Power Unit								
Basement electrical		2- 6v 12						12
1st office		12V					8	33Ah